

Friday, 19/09/2008 2:48:22 PM



User: Linda Lacelle **Process Sheet** : BELT GUIDE **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 42132 **Estimate Number** : 13016 : D36403 **Part Number** P.O. Number - D3640 REVA This Issue : 19/09/2008 S.O. No. : **Drawing Number** Prsht Rev. : NC **Project Number** : N/A : // : A : MACHINED PARTS **Drawing Revision** First Issue Type : 34559 Material Previous Run Each 10 Um: : 22/09/2008 Qty: **Due Date** Written By Checked & Approved By Comment : Est Rev:A New Issue 07-01-15 JLM **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** MDELRINB075X1250 1.0 Delrin Bar Comment: Qty.: 0.4200 f(s)/Unit Total: 4.2000 f(s) Black Delrin Bar 1.250" X .750" BATCH: BAND SAW 2.0 BAND SAW Comment: Cut blank 3.8 " long HAAS CNC VERTICAL MACHINING #1 3.0 HAAS1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA670 & Dwg D3640 Rev: 2-Deburr and Blend rad intersection with deburring tool. 4.0 QC2 INSPECT PARTS AS THEY COME OFF MACHIN Comment: INSPECT PARTS AS THEY COME OFF MACHINE

SECOND CHECK



Comment: SECOND CHECK



08/08/21 (10)

5.0

Dart	Aeros	pace	Ltd

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	ļ								
Part No		PAR #:							
	R	esolution:	Dispositi	on:	_ QA: N/C (closed:		Date: _	
NCR:			WORK ORE	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
			1						
				•					

NOTE: Date & initial all entries

Date: Ųser:

Friday, 19/09/2008 2:48:23 PM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BELT GUIDE

Job Number: 42132

Part Number: D36403

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

7.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Aerospace Ltd


W/O:		WORK ORDER CHANG	BES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	}						
					<u></u>		
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date:	

Disposition: _____ QA: N/C Closed: _____ Date: ____

NCR:			WORK ORDE	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verification	Anneoval	Annesial
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
						•		
							:	

NOTE: Date & initial all entries

Resolution:



Dart Ae	rospace	e Ltd					٠		
W/O:			WO	RK ORDER CHANGE	S]
DATE	STEP	PROC	EDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·	·				
Part No: PAR #:		Fault Category:		NCR: Yes	No DQA:		_ Date:		
	R	lesolution:	_ Disposition	•	QA: N/C Clo	sed:	<u> </u>	Date: _	
NCR:		W	ORK ORDE	R NON-CONFORMAL	NCE (NCR)				:
DATE	STEP	Description of NC		n B	Verific	Verification	Approval	Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
	+		+			+			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	42132
56		
Description: Belt GUIDE	Part Number:	D3640-3
Inspection Dwg: D 3/04/O , Rev:		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
3.58	4.030	3.579				
-40	1/030	UPO				
.200	M- 210	.199				
.31	M030	013			-,-,	1.6
.31	+1- 030	-31				
- 80	1030.	-80				
-03 445	+1-103 × 1/28	.03				
,625	+/010	-630				
-23	1103.	.221				
1.13	+1030	Fi13				
,40	+/030	- 392		·		
					·.	ţ
						·
		,	· · · · · · · · · · · · · · · · · · ·			
					<u></u>	÷
				5		
		ė,			·	

Measured by:	Audited by:	Prototype Approval:	11/
Date: 08/09/21	Date: 08/09/21	Date:	MIN
		Sectional by	Approved
Rev Date Change		Revised by	Whhtasa

